

APPENDIX A
PHOTOGRAPHS

APPENDIX A-1
PHASE I ESA PHOTOGRAPHS



Photograph 1: Fairway Drive and Cassidy's Driving Range. View from west to east.



Photograph 2: Cassidy's Driving Range. View from north to south.



Photograph 3: Fairway Drive, stone barn, and McLaughlin residence. View from east to west.



Photograph 4: View of empty heating oil AST west of stone barn (Parcel #1). View from north-northwest to south-southeast.



Photograph 5: McLaughlin residence. View from southeast to northwest.



Photograph 6: Condemned, vacant residential dwelling. View from south to north.



Photograph 7: Bull Family Cemetery. View from east to west.



Photograph 8: Exterior north of McLaughlin residence. View from northeast to southwest.



Photograph 9: Exterior south of McLaughlin residence. View from east to west.



Photograph 10: Area west of Fairway Drive near southern edge of permitted sand and gravel mine. View from west to east.



Photograph 11: View of contractor supplies stored north of Jerry Medina and Sons occupied staging area (southeastern portion of permitted mine). View from west to east.



Photograph 12: Permitted sand and gravel mine (Parcel #1). View from southeast to northwest.



Photograph 13: View of heating oil AST in basement of Caruso residence (Parcel #1). View from south to north.



Photograph 14: Debris pile 4 (Parcel #1) of roofing waste. View from south to north.



Photograph 15: Debris pile 4 (Parcel #1) of roofing waste. View from south to north.



Photograph 16: Debris pile #6 (Parcel #1) including scrap metal, plastic and metal debris, and a red truck fender. View from east to west.



Photograph 17: Debris pile #7 (Parcel #1), containing a buried water tank. View from south to north.



Photograph 18: Debris Pile #8 (Parcel #1). View from west to east.



Photograph 19: View of Debris Pile #9 (Parcel #1), containing roofing waste, tires, concrete chunks, etc. View from north to south.



Photograph 20: Debris pile #10, containing tires and miscellaneous debris. View from north to south.



Photograph 21: Debris pile #11, containing flexible black pipe. View from east to west.



Photograph 22: View of debris pile #13, abandoned vehicle west of Satterly Creek (Parcel #1). View from southwest to northeast.



Photograph 23: Debris Pile #14 west of pond in southwestern portion of Parcel #1. View from south to north.



Photograph 24: Debris Pile #14 west of pond in southwestern portion of Parcel #1. View from southeast to northwest



Photograph 25: Debris Pile #14 west of pond in southwestern portion of Parcel #1. View from south to north.



Photograph 26: Debris pile #1, containing tires and black flexible pipe south of Caruso residence along northern perimeter of Parcel #2. View from east to west.



Photograph 27: Debris pile #1, containing tires, black flexible pipe, plastic debris, and bagged waste south of Caruso residence along northern perimeter of Parcel #2. View from southeast to northwest.



Photograph 28: Debris pile #1, containing miscellaneous debris south of Caruso residence along northern perimeter of Parcel #2. View from southwest to northeast.



Photograph 29: Vacant, wooded area (Parcel #2). View from east to west.

APPENDIX A-2
TEST PIT INVESTIGATION PHOTOGRAPHS
(MAY 13, 2014)



Photograph 1: View of the dirt, stone, and asphalt observed at TP-1.



Photograph 2: View of the logs and tree debris observed at TP-2.



Photograph 3: Additional view of the tree debris observed at TP-2.



Photograph 4: View of surficial asphalt (right), dimensional lumber, and native soils observed at TP-3.



Photograph 5: View of the native sand observed at TP-4.



Photograph 6: View of the native sand observed at TP-5



Photograph 7: View of the native sand observed at TP-6.



Photograph 8: View of the excavation of TP-7, facing east.



Photograph 9: View of the material excavated from TP-7, facing west.



Photograph 10: View of a portion of the boat debris recovered from TP-7.



Photograph 11: View of the plastic conduit (left) and organic soil observed at TP-8.



Photograph 12: View of the debris observed on the surface of TP-9



Photograph 13: View of the clean sand observed at TP-9